

歐品電子(昆山)有限公司

OUPIIN ELECTRONIC(KUNSHAN) CO.,LTD.

PACKAGING SPECIFICATION (包裝作業規範)

CONFIDENTIAL TOP SECRET

SPEC.NO.(規範編號) Q9111SPP-1075

PAGE 1/4 REV. A

APPLICABLE CUSTOMER (適用客戶) ALL

APPLICABLE PRODUCT (適用產品) 9111-51xxxHxx

PACKAGING CATEGORY (包裝方式) TRAY PLATE PACKING

REVISION HISTORY (修訂履歷)

ECN NO. REV.	PAGE (頁次)							
	1	2	3	4	5			
A	(New Product Issue) 新款发行							

DIVISION (事業單位)	Product Develop (產品開發課)	APPROVED (核准)	CHECKED (審核)	PREPARED (制表)	XFF 02/28'19
-----------------	-------------------------	---------------	--------------	---------------	--------------

歐品電子(昆山)有限公司

OUPIIN ELECTRONIC(KUNSHAN) CO.,LTD.

PACKAGING SPECIFICATION (包裝作業規範)


<input checked="" type="checkbox"/> CONFIDENTIAL		<input type="checkbox"/> TOP SECRET	
PAGE	2/4	REV.	A

SPEC.NO.(規範編號)	Q9111SPP-1075
----------------	---------------

PACKING OPERATION DIAGRAM & INSTRUCTION (包裝作業圖示及說明)

REMARK (備注)

Laying Product Diagram:
(產品擺放圖示)



- 一.Packing Mode:
(包裝方式)
- (1).PE bag 30*40 , CT-1.6 paper bag, drying agent.
(PE袋30*40 , CT-1.6紙箱,干燥劑)
 - (2).Put the way as shown in the products are in the bag
(產品在袋子中擺放方式如圖所示)
 - (3).Stack the XX PE bag filled with product, put them in the paper box in which has been put waterproof bag.
(將放滿產品的XX個PE袋盤疊起,裝入防水袋放入紙箱內)

Minimum supplies label measurement can't exceed the size of label of the other packing box .

最小物料标签尺寸不能超过外包装箱的标签尺寸。

歐品電子(昆山)有限公司

OUPIIN ELECTRONIC(KUNSHAN) CO.,LTD.

PACKAGING SPECIFICATION (包裝作業規範)

CONFIDENTIAL TOP SECRET

SPEC.NO.(規範編號) Q9111SPP-1075

PAGE


3/4

REV.


A

PACKING OPERATION DIAGRAM & INSTRUCTION (包裝作業圖示及說明)

REMARK (備注)




(Drawing 1)
(圖1)



(Drawing 2)
(圖2)

Waterproof Bag
(防水袋)

Paper Box CT-1.6
(紙箱 CT-1.6)



(Drawing 3)
(圖3)

一. Outer Box Packing Mode:

(外箱包裝方式)

- (1). Paper box 1.6 standard 1 PCS, as shown in drawing 2.
(紙箱 1.6 規格 1 PCS, 如(圖2)所示)
- (2). Put one Air column bag in the upper and lower of the paper box, 2PCS in all, as shown in drawing One.
(每箱上下各放一塊氣柱袋, 共 2PCS, 如(圖一)所示)
- (3). Put 1 PCS waterproof in the paper box, as shown in drawing 2.
(紙箱內側放入防水袋 1 PCS, 如(圖2)所示)
- (4). Piled the XX bag plates packed up in the waterproof.
(將放滿產品的 XX 個 PE 袋, 裝入防水袋內)
- (5). Seal the waterproof bag, then put the Air column bag 1PCS on the bag.
(Put 1 PCS Air column bag at the right and left side in the paper box if it is necessary.)
(封上防水袋, 然後放上第二塊氣柱袋)
(必要時, 在紙箱的左右兩側各放一塊氣柱袋)
- (6). Seal the surface of the outer box, as shown in drawing 3.
(將外箱上層封口, 如(圖3)所示)

The form on the right and flank side of the box must be filled correctly and clearly, take actual testing weight as the standard of each box gross weight.

外箱之正麥和側麥所要填寫之項目要填寫正確, 清晰, 每箱之毛重應以實測重量為準。

歐品電子(昆山)有限公司

OUPIIN ELECTRONIC(KUNSHAN) CO.,LTD.

PACKAGING SPECIFICATION (包裝作業規範)

CONFIDENTIAL TOP SECRET

SPEC. NO. (規範編號)		Q9111SPP-1075						PAGE:		4/4	REV.	A
PACKING MATERIAL (包裝材料)			PRODUCT P/N	CT NO.	PACKING N.W.	PACKING QUANTITY (包裝數量)			WEIGHT (重量) kg			
MATERIAL NAME (材料名稱)	PART NUMBER (料號)	Q' TY	(產品料號)	(紙箱規格)	(包材重量)	PCS/BAG	BAG/BOX	PCS/BOX	N. W. /PCS	N. W. /BOX	G. W. /BOX	
PAPER BOXES (紙箱)	CT-1.6	1	9111-5160H1B	CT-1.6	1.85	500	6	3000	0.00274	8.22	10.07	
Pack PE bag (包裝盒)	30*40	----										
Air column bag (氣柱袋)	-----	2										

1.NOTE:
 (注意) When the finished products have been made,take the actual weight as the standard of gross weight in each box.
 (成品出貨時,每箱之毛重應以實測重量為準)
 When the finished products have been made,stick the proper designation list on the box according to product demand.
 (成品出貨時,依據出貨要求貼上相對應的標籤單)
 CT-1.6 Produce goods taiwan. (CT-1.6出貨台灣OP)
 It doesn't influence the manner of packing with the gold-plated way to print word way,Can amalgamate. (印字方式跟鍍金方式不影響包裝方式,可以共用)